

CLASSIFIED MESSAGE

ROUTING

SECRET

1201Z 21 JAN 63

1	INTEL	4
2	DAD	5
3	RB	6

PRIORITY

PRIORITY

IN 63268

DIRECTOR

25X1A

INFO

ACTION: OSA (1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16)

INFO: S/C (17)

TOR: 0003Z 22 JAN 63

25X1A

25X1A

25X1A

PRITY

INFO

CIT

25X1A

PASS TO

25X1A

25X1A

25X1A

25X1A

1. G-3213/5675
2. 9R/0-11-6000/189-10-9-6-2/9L/0-11-6000/188-9-12-5-2

3. D-19/4/75 DEGREES/HTA/2

4. 2.2

5. MEDIUM TO HEAVY/MEDIUM TO HIGH/GOOD TO POOR/SEE PARA 6

6. TAKE RECEIVED AT 1423Z IN COVERED STEEL BOXES. CONDITION GOOD.

DATA CHAMBERS ON BOTH 9R AND 9L INTERMITTENTLY OUT OF FOCUS BEGINNING AT EXPOSURE NR 1821. BOTH 9L AND 9R FRAMES INTERMITTENTLY OUT OF FOCUS FROM INNER EDGE AND EXTENDING INTO APPROXIMATE CENTER OF 9 INCH FRAME WITH FOCUS BECOMING BETTER AS IT APPROACHES OUTSIDE CENTER OF FRAME. APPARENT CAUSE, VACUUM FAILURE. FILM CREASE DUE TO FOLD IN PROCESSOR DRY BOX (HTA/2), FROM FRAME NR 931 TO 938, 9L. SMALL TEARS FRAME NRS 269, 271, 273, 9L DUE TO SP 10/70 PRINTER MALFUNCTION. DESENSITIZED SPOTS REPORTED IN PREVIOUS

SECRET

X1A

S E C R E T

X1A

[REDACTED] (IN 63268)

PAGE TWO

[REDACTED] 20 REPORTS NO LONGER IN EVIDENCE. METERING GOOD.

7. NOT ACCOMPLISHED

8. TAKE TO BE FORWARDED BY COURIER APPROX 1900 LOCAL, 22 JAN 1963.

END OF MESSAGE

S E C R E T